

WWW.NORTHERNDOCKSYSTEMS.COM

**YOUTUBE** INKEDIN



# WORK ORDER #: WO136434





 Address:
 10-3510 29 Street Northeast, Calgary, AB T1Y 7E5
 SERVICE

 Toll-free:
 1 (866) 601-1758 | F: (905) 625-0187 | E: service@northerndocksystems.com

### **Customer Information**

Lafarge Canada Inc.

Toronto, M5W 5K4 ON, Canada

#### **Service Location**

Lafarge Calgary Pipe

Calgary, T2H 3B1 AB, Canada

**Phone Number** 

Contact Scott

#### **Service Details**

Created	11/18/2024 8:30 AM	Last Updated	11/19/2024 4:43 PM
Туре	Local Service	Priority	
Status	Completed	Last Visit Date	11/18/2024
Next Step	No Action Required – internal	Field Specialist	Morgan
Primary Incident Type	Door Service	Signed By	Scott
Customer Asset		P.O #	EMAIL REQUEST - Scott
Scope of Work	Customer Supplied Lift - Large rubber door (Scott to confirm which door upon tech's arrival) - It sounds like one of the chains that connects the spring assembly has jumped off the sprockets.		

## **Execution Notes**

	Details	Content
Created On: 11/18/2024 11:39 AM Created By: Morgan	Door#D1	
<b>Created On:</b> 11/18/2024 11:40 AM <b>Created By:</b> Morgan	Door#D1. The synchro chain has come off the drive sprockets.	
<b>Created On:</b> 11/18/2024 12:03 PM <b>Created By:</b> Morgan	Door#D1. Door make , model and serial number.	
Created On: 11/18/2024 12:26 PM Created By: Morgan	After reinstalling the drive chain and tensioning the springs the drive chain came off the sprocket again. I found a damaged link in the #50 drive chain.	

Created On: 11/18/2024 12:53 PM Created By: Morgan	Customer had #50 chain on site , cut new chain to length and reinstalled.	
Created On: 11/18/2024 1:25 PM	Conclusion: it was the damaged drive chain that caused the issue, after installing a new #50 drive chain and tensioning the springs I ran the door through several cycles testing	
<b>Created By:</b> Morgan	the door and safeties, operation is good.	
	Repairs completed.	