



WORK ORDER #: WO90019



EMERGENCY SERVICE

Address: 415 Ambassador Dr., Mississauga ON L5T 2J3

Toll-free: 1 (866) 601-1758 | **F:** (905) 625-0187 | **E:** service@northerndocksystems.com

Customer Information

18 Wheels Logistics - Burnaby BC
7185 - 11th Ave
Burnaby, V3N 2M5
BC, Canada




Service Location

18 Wheels Logistics - Burnaby BC
7185 - 11th Ave
Burnaby, V3N 2M5
BC, Canada

Service Details

Created	1/24/2022 12:02 PM	Last Updated	1/26/2022 4:02 PM
Type	Local Service	Priority	
Status	Completed	Last Visit Date	1/24/2022
Next Step	No Action Required – internal	Field Specialist	Ed
Primary Incident Type	Door Service	Signed By	
Customer Asset		P.O #	
Scope of Work	Building A, Door 28 won't close.		

Execution Notes

	Details	Content
<p>Created On: 1/24/2022 4:13 PM</p> <p>Created By: Ed</p>	<p>Arrived on site and inspected door. Found door open and unable to close; bent right track, jamb brackets and steel angle was loose from wall. Removed right track and straightened with hammer. Removed broken anchor bolts from angle and installed 3 new wedge anchors. Reinstalled right track.</p>	 A photograph of a white industrial door with the number '28' printed on it. The door is slightly ajar, and the surrounding area shows some wear and tear on the wall and floor.
<p>Created On: 1/24/2022 4:13 PM</p> <p>Created By: Ed</p>	<p>Photo of Door 28.</p>	 A close-up photograph of the vertical track of the door. A red rectangular box highlights the track area, showing some damage and the installation of new components.
<p>Created On: 1/24/2022 4:13 PM</p> <p>Created By: Ed</p>	<p>Second photo of Door 28.</p>	 Another close-up photograph of the vertical track of the door, similar to the previous one, with a red rectangular box highlighting the track area.
<p>Created On: 1/24/2022 5:42 PM</p> <p>Created By: Ed</p>	<p>Tested door. Door is working condition again.</p>	