



WORK ORDER #: WO135909



EMERGENCY SERVICE

Address: 415 Ambassador Dr., Mississauga ON L5T 2J3

Toll-free: 1 (866) 601-1758 | **F:** (905) 625-0187 | **E:** service@northerndocksystems.com

Customer Information

Blank area for Customer Information.

Service Location




Retail Store
Etobicoke
ON, Canada

Service Details

| | | | |
|------------------------------|---|-------------------------|--------------------|
| Created | 11/6/2024 2:57 PM | Last Updated | 11/7/2024 11:30 AM |
| Type | National Service | Priority | P48 |
| Status | Completed | Last Visit Date | 11/7/2024 |
| Next Step | No Action Required – internal | Field Specialist | Danny |
| Primary Incident Type | Door Service | Signed By | |
| Customer Asset | | P.O # | RITM0408539 |
| Scope of Work | The overhead receiving door is hard to close when used by the staff, a technician is required | | |

Execution Notes

| | Details | Content |
|--|---------|---|
| Created On: 11/6/2024 2:58 PM Created By: Silvana | |  |

| | | |
|--|---|--|
| <p>Created On: 11/7/2024 11:28 AM</p> <p>Created By: Danny</p> | <p>Arrived on site and signed in. I had to wait a while until they unloaded the truck. They only have this one rolling steel door. The right side of door wouldn't close all the way down, someone hit the track and bent it so I straightened out the guide us best as possible. The door is in good working order.</p> <p>door face</p> |  |
| <p>Created On: 11/7/2024 11:29 AM</p> <p>Created By: Danny</p> | <p>Bent track</p> |  |
| <p>Created On: 11/7/2024 11:29 AM</p> <p>Created By: Danny</p> | <p>Trailer unloading</p> |  |